
Q65715
TH PREPARING METHOD AND ING METHOD
agust 13, 2001
au yi Mexic
202-293-7060
1 of 7



ű

OOL PATH PREPARING METHOD AND NG METHOD

sexic

-7060

2 of 7

F16.2A






FIG. 2B




SEI, et al Q65715
TOOL PATH PREPARING METHOD AND
MACH* METHOD
Filed: A 13, 2001
Darryl N. arc
202-293-7060

FIG 3



SEI, et al Q65715
TOOL PATH PREPARING METHOD AND
MACHININC "HOD
Filed: Augus, 01
Darryl Mexic
202-293-7060
4 of 7

FIG. 4



S301: IS THERE PROCESSING START COMMAND?

S303; READ IN POSITION DATA OF ROUGHING TOOL AND FINISHING TOOL FROM POSITION DATA TABLE MEMORY

S305: OUTPUT ROUGHING TOOL POSITION COMMAND SIGNAL AND FINISHING TOOL POSITION COMMAND SIGNAL EVERY TIME WHEN THE


NUMBER OF ROTATION REACHES A PREDETERMINED ACCUMULATION NUMBER OF ROTATION 8.

S307: IS FINAL POSITION COMMAND SIGNAL OUTPUTTED?

SEI. et al Q65715

JL PATH PREPARING METHOD AND
CHINING METHOD
d: August 13, 2001


arryl Mexic
202-293-7060
5 of 7



And the true

Mark them 17 that they

SEI, et al Q65715
TOOL PATH PREPARING METHOD AN
MACHINING METHOD
Filed: August 13, 2001
Darryl Mexic
202-293-7060
6 of 7



SEI, et al Q65715
TOOL PATH PREPARI ETHOD AND
MACHINING METHOL
Filed: August 13, 2001
Darryl Mexic
202-293-7060
7 of 7

FIG.7A

